




576-60211-1

A	576/60211	Ram boom < Supersession	1
1	:332/F9110	Kit Service endcap, 80X40 <i>808/00333 is the part number you require. Thanks</i>	1
2	:590/40815	Rod piston 40 dia	1
2A	:831/10002	Bush	1
3	:332/F8974	Piston Head assembly < Supersession	1
4	:826/01183	Dowel 6 X 25	1
5	:2411/7917	Ring wear Supersession >	2
6	:2411/1133	Seal piston < Supersession	1
7	:576/70211	Cylinder ram, 80x706	1
7A	:831/10002	Bush	1
8	:332/F8837	Collar damping	1
9	:2302/0009	O Ring	1
11	:332/C6567	Plug Tapered Dia. 7 x 9.5	2
20	⊘ Not for sale	Paint Consumable Black	1
41	:2401/0605	O Ring	1
42	:1721/0600	Adapter ORFS < Supersession	1
43	:1745/0002	Plug 9/16" O-Ring Boss < Supersession	1
50	: 991/20007	Kit-seal	0

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.