


2025/11/20 10:36:30

1400 > F2-1-1 AXLE ASSEMBLY, 2WD STEERING



1	123/38700	Beam 2wd axle > No Longer Available	1
2	808/00248	Bush	1
3	808/00247	Bush	1
4	123/00363	Carrier left hand > No Longer Available	1
5	120/30003	Axle Stub	1
6	808/00176	Bush < Supersession	4
7	904/07100	Seal < Supersession	4
8	816/60056	Nipple Grease Supersession >	6
9	123/00362	Carrier right hand	1
10	120/30003	Axle Stub	1
11	121/16702	Hub < Supersession	2
12	904/06200	Seal oil Supersession >	2
13	907/04100	Bearing < Supersession	2
14	907/05700	Bearing < Supersession	2
15	120/30006	Washer Supersession >	2
16	1340/0905	Nut Supersession >	1
17	2103/1112	Pin Split 3/16" x 1-3/4" < Supersession	1
18	120/30009	Cap grease Supersession >	1

<https://servicepro.icb.com/products/793991813529601633/parts?filters=%7B%22activePage%3A%22be7ee35c-bc03-49c7-b5c1-52a1efb0efa5%2C%22s...>

<https://servicepro.icb.com/products/793991813529601633/parts?filters=%7B%22activePage%22%3A%22be7ee35c-bc03-49c7-b5c1-52a1efb0efa5%22%22%7D> 5/6

50	1403/0001	Washer Aluminium < Supersession	2
----	-----------	------------------------------------	---