


2026/1/9 14:49:55

8040 ZTS [T2] > B4-1-2 BUCKET LINK



784120

A	 Not for sale	Link Tipping Assembly	1
1	331/49335	Link Tipping L/H Supersession > 333/S6081 found in supersession chain	1
2	331/49334	Link Tipping R/H Supersession >	1
3	589/10360	Link Bucket	1
4	811/90628	Pin Pivot	2
5	811/90629	Pin Pivot	1
6	808/00383	Bush Bronze	2
7	809/00125	Bearing liner 45mm Supersession >	2
8	1315/3420D	Bolt (M10 X 100) < Supersession	4
9	1315/3419D	Bolt M10 x 90mm	2
10	1370/0303D	Nut Lock M10 < Supersession	6
11	1450/0001	Nipple Grease, Straight 1/8 BSP < Supersession	2