




1	⊘ Not for sale	Motor starter Supersession >	1
2A	714/16700	Alternator 12Volt-55Amp sealed	1
2	714/20400	Alternator 65Amp shielded Supersession >	1
3	17/105201	Solenoid E.S.O.S Supersession >	1
4	717/00100	Thermostart < Supersession	1
5	701/37400	Switch temperature	1
6	716/19200	Sender water temperature	1
7	⊘ Not for sale	Switch oil pressure Supersession >	1
8	701/36500	Switch Vacuum Sensor < Supersession	1
9	718/56071	Lead cold start	1
10	701/60014	Sender cold start < Supersession	1
11	721/00447	Lead waxtat cold start	1
13	17/111901	Motor thermal waxtat	1
14	17/111903	Terminal male lucar 90 degree	1
15	17/111904	Nut > No Longer Available	1