




1	729/10655	Battery wet charge 130Ah < Supersession	1
1	729/20655	Battery dry charge 130Ah Supersession >	1
2	260/28401	Clamp battery	1
3	123/07480	Bolt battery M6 x 290mm > No Longer Available	2
4	1410/0001Z	Washer (1/4") Supersession >	2
5	826/01115	Nut Wing M6	2
6	718/56078	Lead battery negative	1
7	718/56101	Lead battery positive	1
9	2410/0205	Grommet Hole Diameter 12.7mm	3
10	826/01144	Cable Tie 200mm < Supersession	4
11	123/03965	Clip	1
12	123/06759	Clip	1
13	821/00487	Clamp 3 Pipe	3
14	821/00488	Plate Clamp	2
15	1315/3214Z	Bolt M6 x 60	2
16	⊘ Not for sale	Stud clamp	2
17	826/01810	Nut Rivet M6	2
18	717/14600	Box fuse link 5 way without fuses < Supersession	1
19	:717/11030	Fuse 30 amp	1
20	:717/11080	Fuse 80 amp male	1
21	717/11050	Fuse 50 amp QTY WAS 3 OFF	2
21A	717/11060	Fuse 60 amp	1

22	817/16574	Decal fuselink	1
23	1315/0307Z	Setscrew M8x25 G8.8 < Supersession Fit to cab mounting bracket.	1
24	1420/0007Z	Washer (M8) Supersession >	2
25	1370/0203Z	Nut Lock, M8 < Supersession	1
26	1370/0101Z	Nut (M6) Supersession >	2
27	1370/0103Z	Nut Lock, M6 < Supersession	2