



1	⊘ Not for sale	No longer available See TI 2/548 for 2CX or 5/400 for 520-50 <i>Please see the below for the only solutions we can offer "ALL THE PARTS NEEDED TO SERVICE THE VALVE ARE CURRENT IN CITREON SHOPS. These are the p/n's, description and prices from Citroen Dealers to overhaul a doseur valve (as they call it); 5424455 CNTRL-UNIT RING 3.88 GBP 95640067 BRAKE PROTECTOR 7.18 GBP The above two are the protector cap (apparently, usual failure point) and its retaining ring The items below are internal O rings 95495759 CNTRL-UNIT SEAL 1.66 GB 95638813 BRAKE O-RING 1.95 GBP 7903065984 BRAKE O-RING 1.04 GBP All of the part above are still available from Citroen Citroen spare companies confirmed no new units available. Repair is the only option. Could also advise them to phone Neil at Vantage Oil in London (0208-5449998) who may be able to offer a reconditioned unit. "</i> > No Longer Available	1
1A	:25/986301	Seal	1
1B	:25/986302	Ring retaining > No Longer Available	1
2	816/15155	Adapter	1
3	816/15155	Adapter	1
4	649/51060	Hose brake	1
5	649/51060	Hose brake	1
6	821/00280	Clamp Hose	4
7	647/02100	Tube PVC 6.3x9.5mm Supersession > To tank	0
8	141/01001	Pipe brake	1
12	141/01002	Pipe brake	1
13	142/00673	Pipe brake	1
14	141/00332	Pipe brake rear cross	1
16	649/26600	Hose brake < Supersession	1
17	816/15125	Connector bulkhead < Supersession	5
18	821/00180	Clamp Top	4

19	649/26600	Hose brake < Supersession	4
20	821/00182	Insert clamp < Supersession	4
21	821/00181	Clamp Base Supersession >	4
22	15/105400	Tee Piece	2
23	⊘ Not for sale	'See Remark' Existing trunnion bolts	8
24	⊘ Not for sale	'See Remark' Not required	0
25	141/01006	Spacer	4