




A	816/50018	Adapter Tee < Supersession	1
1	⊘ Not for sale	'See Remark' Hyd. pump	1
2A	25/107100	Valve solenoid	1
2	⊘ Not for sale	Valve sub-plate side entry <M808271 Supersession >	1
2	25/221224	Valve sub-plate side entry	1
2A	:477/00824	Coil Supersession > 2 off per valve 25/221054 found in supersession chain	1
2F	721/10763	Harness Link	2
2E	1315/0108Z	Setscrew Zinc to fasten item 2	4
2D	1406/0015	Washer Bonded 3/8" <M808271 < Supersession	4
2C	1604/0003	Adapter Male/Male <M808271 Supersession >	1
2B	1606/0003	Adapter <M808271 Supersession >	3
2B	1620/2051	Adaptor 1/4"BSP x 9/16"SAE < Supersession	3
2C	1620/2052	Adaptor 3/8BSP X 9/16 < Supersession	1
2D	:2401/0505	O Ring	4
3	20/916300	Motor hydraulic <M807172 Fitted to LH side of machine > No Longer Available	1

3	20/925273	Motor drive integral sprocket >M807713 Fitted to LH side of machine > No Longer Available	1
4	20/917700	Motor drive <M807172 Fitted to RH side of machine > No Longer Available	1
4	20/925274	Motor drive integral sprocket >M807173 Supersession > Fitted to RH side of machine	1
5	816/50022	Adapter tee <M808234	1
5	816/90136	Adapter tee 3/8M X 3/8M X 1 1/16 replaces items 5 & 13	1
6	816/90055	Adapter 3/4M X 1 1/16 SAE	4
6	1620/0010	Adapter Includes 'O'Ring <M808234 Supersession >	4
6A	:2401/0508	O Ring	1
7	635/33600	Hose low pressure	1
8	1620/0003	Adapter <M808234 Supersession >	3
8	1620/2052	Adaptor 3/8BSP X 9/16 < Supersession	3
9	816/90135	Adapter 4 way replaces 9, 11 & 26	1
9	1605/0014	Adapter <M808234 < Supersession	1
10	1356/0002Z	Nut Backnut(1/4" BSP)	1
11	816/50085	Adapter tee, F/F/M <M808234 Supersession > see item 9	1
12	612/00300	Hose 3/8" BSP 725 mm	2

13	816/17126	Adapter <M808234 see item 5	1
14	611/45800	Hose 1/4"BSP x 350mm	1
14A	816/90013	Adaptor Tee,1/4" BSP < Supersession	1
15	629/28800	Hose High Pressure	1
16	629/28700	Hose High Pressure	1
17	629/28900	Hose High Pressure	1
18	611/26700	Hose 1/4"BSP x 870mm < Supersession	1
19	1620/0002	Adapter <M808234 > No Longer Available	3
19	1620/2051	Adaptor 1/4"BSP x 9/16"SAE < Supersession	3
19A	:2401/0505	O Ring	1
21	816/90288	Adapter 3/4 SAE X 3/8 BSP	2
21	1620/0004	Adaptor G3/8A-3/4UNF(M) <M808234 Supersession >	2
22	816/17128	Adapter (extended)	1
22	816/17134	Adapter <M808234 std. length	1
22	816/90056	Adapter 7/8 BSP X 1 1/16 SAE	1
22A	2401/0507	O Ring	1
24	816/17128	Adapter (extended)	1
24	816/17134	Adapter <M808234 std. length	1
24	816/90056	Adapter 7/8 BSP X 1 1/16 SAE	1
24A	2401/0507	O Ring	1

26	816/50031	Adapter Tee <M808234 Supersession > see item 9	1
27	45/908000	Plug Test Point SAE <i>892/00706 is the mate. Or 892/01234 adaptor w/ hose</i>	1
27	816/55045	Adapter test point <M808234 Supersession >	1
28	25/221216	Valve check O ring 2401/0508	1
28	25/975400	Valve check, 2 bar <M808234 O ring 2401/0508	1
29	1406/0021	Washer Bonded < Supersession	1
31	612/25600	Hose	1
33	611/45000	Hose	1