


2025/11/12 16:48:40

L8-3-1 TURBO, PIPEWORK LJ BUILD



<https://servicepro.icb.com/parts?filters=%7B%22activePage%22%3A%22f6978f80-1440-4a8b-b3d5-577fbb38180e%22%22Specifications.CatalogNum%22%3A%22%22%7D%22> 2/5

[https://servicepro.icb.com/parts?filters=%7B"activePage"%3A"f6978f80-1440-4a8b-b3d5-577fbb38180e"%2C"Specifications.CatalogNum"%3A%](https://servicepro.icb.com/parts?filters=%7B%22activePage)

24	1420/0007Z	Washer (M8) <EU878992J Supersession >	2
25	1425/0007Z	Washer Spring M8 <EU878992J < Supersession	2
26	02/101253	Gasket Supersession >	1
27	⊘ Not for sale	Stud <EU878992J	2
27A	1305/0105Z	Bolt >EU878993J < Supersession	2
28	1340/0101Z	Nut <EU878992J < Supersession	2
29	⊘ Not for sale	Washer spring Supersession >	2
30	1410/0002Z	Washer (5/16" Small) < Supersession	1
31	02/100358	Union < Supersession	1
32	02/101255	Pipe turbo feed <EU878992J > No Longer Available	1
32	⊘ Not for sale	Pipe Turbo feed > No Longer Available	1
33	⊘ Not for sale	Gasket Supersession >	1
34	02/291019	Bolt >EU878993J	2
34	1315/0305	Setscrew M8x20 <EU878992J > No Longer Available	2
35	1425/0007Z	Washer Spring M8 <EU878992J < Supersession	2

<https://servicepro.jcb.com/parts?filters=%7B%22activePage%3A%22f6978f80-1440-4a8b-b3d5-577fbb38180e%2C%22Specifications.CatalogNum%3A%22%7D>