


2025/11/11 13:31:15

A745-25-1 POLE PLANTER DETAILS BEAM, CLAMP



128-Y5668-2

A	⊘ Not for sale	Clamp Beam Assembly	1
10	128/Y5579	Beam Clamp	1
20	⊘ Not for sale	Clamp Assembly	2
30	1315/3712Z	Bolt M16x50M	8
40	1420/0011Z	Washer (M16) < Supersession	28
50	1370/0603Z	Nut Lock, M16 < Supersession	14
60	612/80078	Hose	4
70	826/01144	Cable Tie 200mm < Supersession	6
80	1315/0301Z	Screw Hexagon M8 X 12mm	1
90	1420/0007Z	Washer (M8) Supersession >	1
100	531/38500	WA Pipe Cluster	1
110	40/304054	Bush	2
120	813/00433	Seal Pivot Pin 65x80x4 < Supersession	2
130	335/Y9416	Bracket Guide	2
140	826/10526	Bolt (M16 x 2 x 80)	6

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.