




A	160/00441	G.A ACCELERATOR CONTROLS	1
1	335/05196	Pedal accelerator	1
2	160/00486	Bearing accelerator pedal	2
3	1315/3312Z	Bolt M8x50 < Supersession	2
4	1370/0203Z	Nut Lock, M8 < Supersession	2
5	161/00028	Bracket cable reaction cab	1
6	814/00359	Spring	1
7	910/60182	Cable throttle control assembly	1
8	:2101/0002	Pin clevis	1
9	:2103/0305	Pin Split 1/16 x 1/2 < Supersession	1
10	:1340/0002Z	Nut < Supersession	2
11	:1411/0002Z	Washer (5/16" Medium) Supersession >	2
12	:1370/0201Z	Nut Standard M8 Supersession >	1
13	814/10179	Spring Overload	1
14	331/40859	Bracket throttle reaction	1
15	1315/0205Z	Setscrew M6x20 Supersession >	3
16	1420/0006Z	Washer Plain M6 Supersession >	3
17	1370/0103Z	Nut Lock, M6 < Supersession	3
18	826/01144	Cable Tie 200mm < Supersession	2

