




A	⊘ Not for sale	Assembly main electrics	1
1	⊘ Not for sale	Harness main JZ235 T3 Supersession >	1
2	701/80372	Switch Auto Mode pressure 22bar Supersession > Auto mode	1
3	701/80373	Switch pressure 5bar 1/4" BSP Supersession > Swing, boom up boom down	1
4	701/80374	Switch Upper servo pressure 12bar Supersession > Excavating	1
5	701/80375	Switch Travel pressure 20bar Supersession > Travel	1
6	701/80462	Switch pressure 298bar 1/4" BSP Supersession > Auto boost	1
7	JHN0048	Bolt < Supersession	1
8	JHR0128	Bolt Flanged Hex M6X20 < Supersession	5
9	JHR0162	Cable Battery Lead Clamp And Cover < Supersession Battery to battery cable	1
10	JRR0057	Cable battery lead clamp and cover < Supersession	1
11	JRR0074	Harness radio	1
12	826/01144	Cable Tie 200mm < Supersession	8
13	KAR0152	Grommet	2
14	826/01143	Cable Tie 300mm < Supersession	9
15	KHR0139	Hose corrugated Supersession >	3

16	KHR0737	Screw Pan Head < Supersession	22
17	⊘ Not for sale	Clip	1
18	KHR1326	Clamp SPL 18mm dia	2
19	KHR1327	Clamp 22mm dia. 22mm dia	4
20	KHR1407	Clamp 25mm 25mm dia	2
21	KHR1408	Clamp 30mm dia. 30mm dia	1
22	KHR1444	Clamp 12mm dia. 12mm dia	3
23	KHR1445	Clamp 15mm dia. 15mm dia	1
24	KHR1451	Cable Earth	1
25	KHR1588	Clip	1
26	KHR1716	Cap Terminal	2
27	1316/0301D	Screw	2
28	1316/0303D	Setscrew M8 x 16 G10.9	3
29	1316/0305D	Setscrew M8 X 20 G10.9 < Supersession	1
30	1316/0307D	Setscrew M8 x 25 G10.9	2
31	1316/0407D	Setscrew M10 X 25mm < Supersession	2
32	1316/0505D	Setscrew M12 x 20 G10.9	1
33	1316/0507D	Setscrew M12 x 25 Grade 10.9	2
34	1406/0015	Washer Bonded 3/8" < Supersession	1
35	1420/0007D	Washer M8 < Supersession	8
36	1420/0008D	Washer M10 < Supersession	2
37	1420/0009D	Washer Plain M12 < Supersession	1

38	6063/0006Z	Washer starlock	3
39	6063/0007Z	Washer starlock	1
40	6063/0009Z	Washer starlock < Supersession	1
41	6012/0298Z	Screw pan head	3
42	701/80328	Switch Overheat Warning	1
42A	:1406/0015	Washer Bonded 3/8" < Supersession	1
43	⊘ Not for sale	'See Remark' Hazard Beacon See Index C3	1
44	716/30129	Sensor Temperature M16 <i>Hyd Oil Sensor</i>	2
45	718/20025	Cable battery negative	1
46	718/20026	Cable battery positive to battery relay	1
47	721/10453	Harness Boom Working Lights	1
50	821/00367	Clip	1
51	826/01347	Tie Cable 160mm <i>For welded stud push fit</i>	30
52	⊘ Not for sale	'See Remark' Battery See Index C1	1
53	⊘ Not for sale	'See Remark' Engine earth See Index C2	1
54	717/20152	Horn 24 volt Supersession >	1
55	KHR1589	Fuse 25 AMP	1
56	KHR1592	Fuse 65 AMP	1
57	331/42101	Bracket	2
58	1315/0305D	Setscrew M8 x 20mm < Supersession	4
59	1420/0007D	Washer M8 < Supersession	4

