


2026/1/5 16:20:55

V150-1-1 CAMSHAFT ASSEMBLY



320-22205-1

A	⊘ Not for sale	Assembly camshaft tiner	1
1	320/03685	Camshaft Assembly	1
2	320/03524	Tappet Valve	8
3	320/03677	Rod Push < Supersession	8

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.