




332-F3137-1

A	⊘ Not for sale	Valve Pilot Assembly	1
1	332/F6361	Valve Pilot < 23-May-2013 Supersession > 402/P6059 found in supersession chain	1
1	400/B1832	Valve Pilot > 24-May-2013 Supersession > 402/P6059 found in supersession chain	1
2	816/90271	Adapter	1
3	401/C8565	Accumulator 0.24ltr 5.0bar > 25-June-2019	1
3	903/11150	Accumulator 0.25 Litre 5 bar < 24-June-2019 Supersession >	1
4	816/90618	Adaptor Elbow G1/4A x 9/16UNF < Supersession	2
5	45/908000	Plug Test Point SAE <i>892/00706 is the mate. Or 892/01234 adaptor w/ hose</i>	2
6	1620/2051	Adaptor 1/4"BSP x 9/16"SAE < Supersession	2
7	1620/2052	Adaptor 3/8BSP X 9/16 < Supersession	1
8	1420/0007Z	Washer (M8) Supersession >	2
9	332/H0451	Bracket Pilot Valve	1
10	1370/0303Z	Nut Lock M10 Supersession >	2
11	1420/0008Z	Washer Plain M10 Supersession >	4
12	1315/0305Z	Setscrew M8 x 20 G8.8 < Supersession	2
13	1315/0412Z	Setscrew M10x50	2

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.