

2026/1/8 10:30:46

214 [T0] > B4-10-5 BOOM LOCK IN CAB CONTROLS SIDESHIFT

<https://servicepro.icb.com/products/793991813529601401/parts?filters=%7B%22activePage%22%3A%22a54c48c0-67bb-4efa-9050-14d5927a1679%22%22%7D> 3/5

<https://servicepro.icb.com/products/793991813529601401/parts?filters=%7B%22activePage%22%3A%22a54c48c0-67bb-4efa-9050-14d5927a1679%22%2C%22...> 4/5

34	529/38603	Clip Supersession >	1
35	1370/0202Z	Nut Thin (M8) < Supersession	1
36	123/04894	Plunger < Supersession 14'0" Exavator end	1
37	1315/3311Z	Bolt (M8 X 45) < Supersession	2
38	1370/0203Z	Nut Lock, M8 < Supersession	2
39	123/01354	Lock boom side shift > No Longer Available	1
40	811/50220	Pin	2
41	2102/0919	Pin < Supersession	2
42	828/00150	Stop Rubber Buffer < Supersession	1
43	826/00512	Pin Linch	1