


2025/10/13 13:18:35

802 &gt; J1-2-1 IDLER SPROCKET &amp; TENSIONER UNIT



H05282

From: M732001 To: M732449

<https://servicepro.icb.com/products/793991813529601976/parts?filters=%7B%22activePage%22%3A%229e65b29a-63be-4090-8e4d-e9284cd757f8%22%22%7D> 2/3

|    |                |                                         |
|----|----------------|-----------------------------------------|
| 7  | ::233/26603    | Sprocket idler                          |
| 8  | ::232/26403    | Shaft idler                             |
| 9  | ::916/05500    | Bearing                                 |
| 10 | ::813/00385    | Seal lip                                |
| 11 | ::826/01251    | Pin tension                             |
| 12 | ::2203/1068    | Circlip Internal<br>< Supersession      |
| 13 | ::1406/0008    | Washer Bonded 10mm<br>< Supersession    |
| 14 | ::1391/3401Z   | Capscrew<br>M10                         |
| 15 | ⊘ Not for sale | Unit recoi assembly 1761kgf             |
| 16 | :232/21900     | Shaft spring support                    |
| 17 | :232/21601     | Cap end                                 |
| 18 | ⊘ Not for sale | Spring recoil                           |
| 19 | :826/01252     | Nut castle<br>M24                       |
| 20 | :2103/1112Z    | Pin cotter<br>Supersession >            |
| 21 | :1403/0003     | Washer Aluminium (I/D=17mm)             |
| 22 | :232/23700     | Valve recoil adjuster<br>< Sunersession |