




A	⊘ Not for sale	Turbocharger Assembly	1
10	320/06376	Turbocharger BV55 (High Actuator)	1
10	320/06376R	Reman Turbo - BV55 Reman	1
10b	320/A6063	Turbocharger service kit BV55 linkage	1
10a	320/A6064	Turbocharger service kit BV55 High Actuator	1
20	320/06053	Gasket Single TC To Manifold < Supersession	1
30	320/06007	Stud M8 x 75	4
40	320/06008	Nut Lock M8 Special	4
50	826/11384	Stud M10 X 37 < Supersession	3
60	320/A4217	Adaptor Assembly Turbo Oil < Supersession	1
70	320/00852	Gasket Drain Pipe To Turbo	1
80	320/00851	O Ring Alternative Part	1
80	320/A0512	O Ring 17 X 2.0, PTF	1
90	1317/3203V	Bolt M6 x16 < Supersession	2
100	7243/0195	Clip Tree Supersession >	1

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.