




1	⊘ Not for sale	Pedal brake	1
2	811/50237	Pivot pin	1
3	1315/3310Z	Bolt M8 x 40mm	2
4	1370/0203Z	Nut Lock, M8 < Supersession	1
5	831/00065	Bearing Supersession >	2
6	⊘ Not for sale	No longer available See TI 2/548 for 2CX or 5/400 for 520-50 <i>Please see the below for the only solutions we can offer "ALL THE PARTS NEEDED TO SERVICE THE VALVE ARE CURRENT IN CITREON SHOPS. These are the p/n's, description and prices from Citroen Dealers to overhaul a doseur valve (as they call it); 5424455 CNTRL-UNIT RING 3.88 GBP 95640067 BRAKE PROTECTOR 7.18 GBP The above two are the protector cap (apparently, usual failure point) and its retaining ring The items below are internal O rings 95495759 CNTRL-UNIT SEAL 1.66 GB 95638813 BRAKE O-RING 1.95 GBP 7903065984 BRAKE O-RING 1.04 GBP All of the part above are still available from Citroen Citroen spare companies confirmed no new units available. Repair is the only option. Could also advise them to phone Neil at Vantage Oil in London (0208-5449998) who may be able to offer a reconditioned unit. "</i> > No Longer Available	1
6A	:25/986301	Seal	1
6B	:25/986302	Ring retaining > No Longer Available	1
7	141/00703	Buffer rubber	1
8	1425/0007Z	Washer Spring M8 < Supersession	1
9	1370/0102Z	Nut Thin, M6 < Supersession	1
10	141/00772	Plunger	1
11	814/00360	Spring	1
17	814/00144	Spring Tension	1
18	701/80191	Switch brake light 12 volt green top Supersession > 701/80266 found in supersession chain	1

19	 Not for sale	'See Remark' Washer	1
20	1420/0006Z	Washer Plain M6 Supersession >	1
21	913/00703	Clip < Supersession	1
22	1315/0308Z	Setscrew M8 x 30 To secure item 17	1
23	1420/0006Z	Washer Plain M6 Supersession >	1
24	1370/0201Z	Nut Standard M8 Supersession >	1