




A	⊘ Not for sale	G.A BONNET	1
1	128/15282	Bonnet loxam red Loxam red > No Longer Available	1
1A	⊘ Not for sale	Vent assembly air induction	1
1	128/C6611	Bonnet Supersession >	1
1B	⊘ Not for sale	Screw No 8 x 1 1/4" to hold 1A to 1 > No Longer Available	2
2	926/51401	Gasket air intake Supersession >	1
4	331/26981	Catch bonnet < Supersession	1
5	1315/0301Z	Screw Hexagon M8 X 12mm	2
6	1420/0007Z	Washer (M8) Supersession >	2
7B	128/17722	Rail bonnet upper LH Loxam red	1
7A	128/17749	Rail bonnet lower LH Loxam red	1
7B	346/00563	Rail bonnet upper LH yellow see TI 2/503 Supersession >	1
7A	346/00565	Rail bonnet lower LH yellow see TI 2/503 Supersession >	1
8B	128/17745	Rail bonnet upper RH Loxam red	1
8A	128/17751	Rail bonnet lower RH Loxam red	1
8B	346/00564	Rail bonnet upper RH yellow see TI 2/503 Supersession > 332/P5260 found in supersession chain	1
8A	346/00566	Rail bonnet lower RH yellow see TI 2/503 Supersession >	1
9	826/11692	Screw Torx M6x35	4
10	826/01465	Retainer "U" Nut	4

12	1420/0006Z	Washer Plain M6 Supersession >	2
13	1315/0207Z	Setscrew M6x25 Supersession >	2
15	826/01810	Nut Rivet M6	2
16	128/14553	Hinge bonnet RH	1
17	128/14552	Hinge bonnet LH	1
18	335/07952	Hinge torsion beam	1
20A	331/60391	Ball fitting 10 X M8	1
20	331/66727	Strut gas 235-390 < Supersession	2
21	331/66785	Strut gas 585x327 < Supersession	1
22	826/11284	Screw M8x16	8
23	826/01249	Nut Rivet M10	4
24	1315/0409Z	Setscrew M10 x 35mm < Supersession	4
25	1420/0008Z	Washer Plain M10 Supersession >	4
26	1371/0203Z	Nut Lock (M8)	3
27	1420/0007Z	Washer (M8) Supersession >	4
28	823/10639	Washer	2
44	1418/0011Z	Washer Locking (5/16")	2
45	1370/0202Z	Nut Thin (M8) < Supersession	4
51	1370/0201Z	Nut Standard M8 Supersession >	2