


2025/9/30 14:58:29



1400 > E4-2-7 RAM, BACKHOE 14'0"



067400

<https://servicepro.icb.com/products/793991813529601633/parts?filters=%7B%22activePage%22%3A%229e9659db-a89a-4e1d-a85d-7c75081dd620%22%2C%22...> 3/8

<https://servicepro.icb.com/products/793991813529601633/parts?filters=%7B%22activePage%3A%22%3A%229e9659db-a89a-4e1d-a85d-7c75081dd620%22%2C...>

2	⊘ Not for sale	Pipe rod side Standard. Welded to cylinder
2	::658/00495	Pipe piston side
2	::658/00495	Pipe piston side Standard. Welded to cylinder
2	⊘ Not for sale	Pipe ex dipper <M325160 Supersession > For use with Extending Dipper m/c's.
2	⊘ Not for sale	Pipe < Supersession Standard. Welded to cylinder
2	⊘ Not for sale	Pipe ex dipper <M325160 For use with Extending Dipper m/c's
2	⊘ Not for sale	Pipe ex dipper <M310999 Welded to cylinder
2	⊘ Not for sale	Pipe cylinder side Standard. Welded to cylinder
2	⊘ Not for sale	Pipe rod side Standard. Welded to cylinder
2	⊘ Not for sale	Pipe cylinder side
2	⊘ Not for sale	Pipe rod side <M306026 (See foot note)
2	⊘ Not for sale	Pipe ex dipper <M310999
2	⊘ Not for sale	Pipe rod side <M310999 > No Longer Available
2	⊘ Not for sale	Pipe
2	⊘ Not for sale	Pipe rod side > No Longer Available
2	::658/00876	Pipe bucket ram rod side > No Longer Available

<https://servicepro.icb.com/products/793991813529601633/parts?filters=%7B%22activePage%3A%22%3A%229e9659db-a89a-4e1d-a85d-7c75081dd620%22%2C...>

<https://servicepro.icb.com/products/793991813529601633/parts?filters=%7B%22activePage%22%3A%229e9659db-a89a-4e1d-a85d-7c75081dd620%22%22%7D> 7/8

16B	826/01179	Dowel 8.0 x 25.0 < Supersession
16A	826/01180	Dowel