




A	816/50018	Adapter Tee < Supersession	1
1	⊘ Not for sale	'See Remark' Hyd. pump	1
2	25/104000	Valve pressure reducing > No Longer Available	1
3	20/911500	Motor drive LH colour code RED <M751817	1
3	20/914400	Motor drive LH > No Longer Available	1
4	⊘ Not for sale	Motor drive RH colour code YELLOW <M751817 > No Longer Available	1
4	20/914500	Motor drive RH > No Longer Available	1
5	816/50022	Adapter tee	1
6	1620/0010	Adapter Includes 'O'Ring Supersession >	4
6A	:2401/0508	O Ring	1
7	635/33600	Hose low pressure	1
8	1620/0003	Adapter Supersession >	3
9	1605/0014	Adapter < Supersession	1
10	1356/0002Z	Nut Backnut(1/4" BSP)	1
11	816/50085	Adapter tee, F/F/M Supersession >	1
12	612/00300	Hose 3/8" BSP 725 mm	2
13	816/17126	Adapter >M751601	4
13	816/60066	Adapter <M TBA Mar. 98	1

13	1620/0010	Adapter Includes 'O'Ring Supersession >	1
14	611/27200	Hose 1/4"BSP x 820mm	2
15	621/40700	Hose extra high pressure <M751600	1
15	⊘ Not for sale	Hose Ultra H.P. <M752126	2
15	629/28800	Hose High Pressure >M752127	1
16	621/40800	Hose extra high pressure <M751600	1
16	⊘ Not for sale	Hose Ultra H.P. <M752126	1
16	629/28700	Hose High Pressure >M752127	1
17	621/40900	Hose extra high pressure <M751600	1
17	624/41400	Hose Ultra H.P. <M752126	1
17	629/28900	Hose High Pressure >M752127	1
18	621/41000	Hose extra high pressure <M751600	1
19	1620/0002	Adapter > No Longer Available	3
21	1620/0004	Adaptor G3/8A-3/4UNF(M) Supersession > 1620/2053 found in supersession chain	2
22	816/17121	Adapter extended <M752126	2
22	816/17128	Adapter (extended) >M751601	1
22	816/17134	Adapter <M751600	1
24	816/17121	Adapter extended <M752126	1

24	816/17128	Adapter (extended) >M751601	1
24	816/17134	Adapter <M751600	1
26	816/50031	Adapter Tee Supersession >	1
27	816/55045	Adapter test point Supersession >	1
28	25/975400	Valve check, 2 bar	1
29	1406/0021	Washer Bonded < Supersession	1
33	611/45000	Hose	1
34	612/33700	Hose	1
35	612/24800	Hose	1
37	816/60066	Adapter >M751601	1