


8014 [T0] > D1-4-1 MOUNTING SERVO CONTROLS



H17863

1	233/09400	Bracket RH Pod	1
2	233/09900	Bracket L.H. Pod	1
3	⊘ Not for sale	Mounting pod lh > No Longer Available	1
4	⊘ Not for sale	Mounting pod rh	1
5	828/00134	Stop rubber	4
6	⊘ Not for sale	Mounting strut	1
7	233/08802	Strut gas MTBA	1
7	331/13337	Strut gas 8015 M820244 on	1
7	331/13337	Strut gas 8018 M801175 on	1
7	331/13337	Strut gas 8014 M791705 on	1
7	331/13337	Strut gas 8016 M728958 on	1
7	331/13337	Strut gas 8017 M800201 on	1
8	809/10065	Bush	4
9	1411/0005Z	Washer (1/2" Medium) < Supersession	2
10	823/00417	Washer spring Supersession >	2
11	1315/0507Z	Setscrew M12 x 25 < Supersession	2
12A	⊘ Not for sale	'See Remark' Cover, pod, RH	1
12	233/08803	Lever pod, LH	1

<https://servicepro.icb.com/products/793991813529601137/parts?filters=%7B%22activePage%3A%22c8390d5f-6663-4695-93c8-ffad9b55ab97%22se...>

[https://servicepro.jcb.com/products/793991813529601137/parts?filters=%7B"activePage"%3A"c8390d5f-6663-4695-93c8-ffad9b55ab97"%2C"se...](https://servicepro.jcb.com/products/793991813529601137/parts?filters=%7B%22activePage%22%3A%22c8390d5f-6663-4695-93c8-ffad9b55ab97%22%2C%22se...) 4/4