




2	716/30146	Sensor fuel level AR,AK engine builds	1
3	:103/77101	Gasket Fuel Level Sensor Supersession >	1
4	826/00520	Screw	6
6	⊘ Not for sale	NSP	0
7	1411/0005Z	Washer (1/2" Medium) <M936295 < Supersession Foot brake	1
8	⊘ Not for sale	Switch brake light/Dump black top <M936295 Supersession > Foot brake light	1
8	701/80342	Switch Proximity Foot/Parkbrake >M936296 Foot brake light. > No Longer Available	1
8	701/80342	Switch Proximity Foot/Parkbrake Hand brake light > No Longer Available	1
9	1340/0402Z	Nut Thin (1/2" UNF) <M936295 < Supersession Foot brake	2
10	701/80319	Switch oil pressure,M12 green body,Deutsch Supersession > Transmission pressure	1
10A	1406/0011	Washer Bonded 1/4"BSP < Supersession	1
13	701/80324	Switch oil temp 5/8"UNF Deutsch connector Transmission temperature	1
14	1406/0018	Washer Bonded (1/2" BSP) < Supersession	1
17	701/80312	Switch proximity 3-pin triangular Deutsch connector AWS axles only- front & rear	2

