




A	⊘ Not for sale	Dipper extending assembly	1
1	⊘ Not for sale	Dipper sliding assembly	1
2	⊘ Not for sale	Dipper fixed assembly	1
3	⊘ Not for sale	Link Bucket Assy <i>232/03901 has an eye end hole.</i> > No Longer Available	1
4	331/23311	Link Tipping	2
5	232/02007	Pin pivot < Supersession	2
6	1315/3420D	Bolt (M10 X 100) < Supersession	2
7	1370/0303D	Nut Lock M10 < Supersession	3
8	1450/0001	Nipple Grease Straight 1/8" < Supersession	4
11	232/01100	Pin pivot	2
12	811/50336	Pin pivot	1
13	556/60486	Ram Bucket 1CX	1
14	333/W5821	Dipper Extention Ram	1
15	232/03907	Bush	4
16	290/00752	Spacer 36mm long	1
17	290/00753	Spacer 51mm long	1
18	232/03906	Bush	2
19	290/00751	Spacer 44mm long	1
21	696/01225	Spacer	2
22	1315/3417Z	Bolt M10 x 75 < Supersession	1
23	819/00051	Shim Supersession >	6

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.