




A	342/00050	WORK LIGHTS G.A	1
1	700/50029	Work lamp	1
2	:720/10061	Bulb , High Beam, 12V 55W, H3 (ECE R37, FMVSS 108 with DOT) < Supersession	1
3	:700/10103	Spring	1
4	:1315/0405D	Setscrew M10 x 20 G8.8 < Supersession	1
5	:1370/0303D	Nut Lock M10 < Supersession	1
6	:1413/0003D	Washer 3/8"	2
7	:1315/3313D	Bolt M8 x 55mm	1
8	:1370/0203D	Nut Lock M8 < Supersession	1
9	:1413/0003D	Washer 3/8"	1
11	331/40908	Bracket work light mounting right hand	1
12	⊘ Not for sale	Bracket work light mounting left hand > No Longer Available	1
13	1315/0305D	Setscrew M8 x 20mm < Supersession	4
14	1370/0203D	Nut Lock M8 < Supersession	4
15	1420/0007D	Washer M8 < Supersession	4
16	904/20209	Seal Cable	2