




980-A3948-4

A	980/A3948	Kit-air conditioning	1
10	:128/V4830	Heater assembly, aircon ABI Supersession >	1
20	:30/925766	Condenser	1
30	:332/C9571	Bracket mounting, condenser LH CAC	1
40	:332/C9526	Bracket mounting, condenser RH CAC	1
50	:1420/0006Z	Washer Plain M6 Supersession >	8
60	:1315/3210Z	Bolt (M6 x 40)	8
80	:826/01194	U Bolt	1
90	:30/925633	Drier Receiver	1
110	:320/08562	Compressor A/C, 12V < Supersession	1
120	:1317/3320Z	Bolt flanged, M8 x 100	3
140	:1420/0007Z	Washer (M8) Supersession >	22
150	:1315/0307Z	Setscrew M8x25 G8.8 < Supersession	6
160	:821/00214	Clamp base	1
170	:821/00213	Clamp top	1
180	:821/00215	Insert clamp	1
200	:1315/0305Z	Setscrew M8 x 20 G8.8 < Supersession	4
210	:333/A3986	Manual fitting instructions	1
220	: 320/08609	Belt drive L=1995 < Supersession 2WS T4i	1
230	:320/08503	Pulley Cooling Fan Supersession >	1

240	:400/G3280	Control Panel , Heater < Supersession	1
280	:332/G6513	Bracket mounting receiver/drier	1
290	:1315/0308Z	Setscrew M8 x 30	2
300	:1370/0203Z	Nut Lock, M8 < Supersession	6
310	:7210/0067	Mount Clip	1
320	:320/08606	Belt drive L=2110 Supersession > AWS T4i	1
330	:400/Y4690	Hose AC 1475mm Supersession >	1
340	:649/51772	Hose aircon	1
350	:400/Y4592	Hose A/C, 800mm < Supersession	1
360	:332/D3213	Hose A/C, 2900mm	1
370	:320/08937	Belt Drive 8PK2022 AR4 Supersession > 2WS T4F	1
380	:320/08939	Belt Drive 8PK2138 AR4 Supersession > AWS T4F	1

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.