




A	⊘ Not for sale	Ram dipper use with HBCV 100mm cyl x 60mm rod Supersession >	1
1	559/60146	Ram assembly, dipper <JUN-2002 Supersession >	1
1	559/60172	Ram dipper, 100x60 1898OC 1152.5CC Supersession >	1
2	:559/70077	Cylinder dipper <JUN-2002	1
2	:559/70171	Cylinder dipper ram Supersession >	1
2A	⊘ Not for sale	None serviced part	1
2B	⊘ Not for sale	None serviced part	1
3	:809/00179	Bearing 60x70x90L	1
4	:590/40155	Rod piston 60mm dipper ram <JUN-2002 < Supersession	1
4	:590/40583	Rod piston Supersession > 590/40771 found in supersession chain	1
5	:809/00127	Bearing liner 50mm pivot bore < Supersession	2
6	:594/14025	Kit - end cap assembly service < Supersession	1
7	:559/00105	Restrictor Supersession >	1
8	:559/00104	Spring	1
9	:595/10057	Head piston	1
10	:1450/0001	Nipple Grease Straight 1/8" < Supersession	2
11	:991/00145	Kit-seal ram assembly Supersession > For component parts see fram E4-13-18	1

12	:826/01179	Dowel 8.0 x 25.0 < Supersession	1
13	:813/00427	Seal Grease	2
14	:813/00426	Seal Pivot Pin 50 X 60 X 5	2