




176352

1	⊘ Not for sale	No longer available See TI 2/548 for 2CX or 5/400 for 520-50 <i>Please see the below for the only solutions we can offer "ALL THE PARTS NEEDED TO SERVICE THE VALVE ARE CURRENT IN CITREON SHOPS. These are the p/n's, description and prices from Citroen Dealers to overhaul a doseur valve (as they call it); 5424455 CNTRL-UNIT RING 3.88 GBP 95640067 BRAKE PROTECTOR 7.18 GBP The above two are the protector cap (apparently, usual failure point) and its retaining ring The items below are internal O rings 95495759 CNTRL-UNIT SEAL 1.66 GB 95638813 BRAKE O-RING 1.95 GBP 7903065984 BRAKE O-RING 1.04 GBP All of the part above are still available from Citroen Citroen spare companies confirmed no new units available. Repair is the only option. Could also advise them to phone Neil at Vantage Oil in London (0208-5449998) who may be able to offer a reconditioned unit. "</i> > No Longer Available	1
1A	:25/986301	Seal	1
1B	:25/986302	Ring retaining > No Longer Available	1
2	816/15155	Adapter	1
3	816/15155	Adapter	1
4	649/24500	Hose	1
5	649/24500	Hose	1
6	821/00280	Clamp Hose	4
7	647/02100	Tube PVC 6.3x9.5mm Supersession > To tank	0
12	141/00330	Pipe chassis to front tee	1
13	⊘ Not for sale	Pipe brake chassis to rear tee > No Longer Available	1
14	141/00332	Pipe brake rear cross	1
15	⊘ Not for sale	Pipe brake front cross pipe <M657301 > No Longer Available	1
15	141/00686	Block adapter	1
16	141/00334	Pipe brake front hose link > No Longer Available	1

17	141/00334	Pipe brake front hose link > No Longer Available	1
18	140/00954	Pipe brake	4
19	649/23500	Hose brake	4
20	140/00953	Bracket	4
21	⊘ Not for sale	Guard brake pipe > No Longer Available	4
22	15/105400	Tee Piece	2
23	⊘ Not for sale	'See Remark' Existing trunnion bolts	8
24	826/00622	Nut	11
25	821/00069	Clip pipe	2
26	655/00343	Spacer <M657302	1
27	1315/0311Z	Setscrew <M657301 < Supersession	1