




A	557/60307	Ram , Dipper, 90 X 60 Supersession >	1
1	590/40980	Rod , Piston, 60X1020 <i>1 x 809/02032 bearing and 2 x 813/00426 dust seals required for the pivot pin</i>	1
2	334/H0237	Assembly End Cap 90 x 60 Supersession >	1
2A	808/00393	Bearing	1
3	595/27300	Head Piston 90 x 50	1
4	826/01179	Dowel 8.0 x 25.0 < Supersession	1
5	2411/7918	Ring Wear 90 x 9.4 < Supersession	2
6	2411/1135	Seal Piston 90 x 6 < Supersession	1
7	557/70307	Cylinder , 90 X 955 <i>1 x 809/02015 bearing and 2 x 813/00426 dust seals required for the pivot pin</i>	1
7A	809/02015	Bearing 50-60-88	1
8	551/90107	Plate orifice 27.4 x 15 x 5.8mm < Supersession	1
9	821/00462	Clip 31.1mm	1
10	334/H0592	Collar Ground Damping	1
11	2302/0155	O Ring	1
12	332/C6567	Plug Tapered Dia. 7 x 9.5	0
20	⊘ Not for sale	Paint Consumable Black	0
42	1721/1000	Adaptor ORFS Female	2
43	2401/0607	O Ring	2
50	991/20048	Kit , Seal	0

Following JCB's Serviceability Review, only those items with part numbers are available to purchase for this Component. For any other items please purchase the next available parent assembly.