




0	⊘ Not for sale	Drawing Axle location ALSO PAINT PLANT No.	0
A	440/M4500	GA Axle Hydrostatic Supersession >	1
1	458/T3615	Axle Beam Machining < Supersession	1
2	458/M7214	MOTOR CARRIER - MACH MOTOR CARRIER - MACH < Supersession	2
3	907/50700	Bearing Taper Rolling < Supersession	4
4	904/50011	Seal trunnion	4
5	440/00103	Trunnion	4
6	1321/0408Z	Setscrew ITEM 5	16
8	440/20505	Ram power trackrod < Supersession	1
9	1391/3518	Screw cap ITEM 8	4
11	458/M9602	Steering Link Assembly < Supersession	2
13	458/N7750	Pin Link < Supersession	2
15	1420/0012Z	Washer M20 < Supersession	2
16	826/00818	Pin Tension	4
17	458/N7751	Pin Steer Link < Supersession	2
18	826/01784	Pin tension	2
19	445/14001	Dowel < Supersession	2
20	440/20805	Pad wear	2
22	401/J3033	Motor Wheel 500cc POCLAIN < Supersession	2

23	1392/3510	Screw M12x40	20
34	4003/2000	Grease High Pressure > No Longer Available	1
35	817/02980	Plate Serial	1
36	826/01231	Rivet Chobert	2
37	835/00017	Cap Grease Nipple Supersession >	8
38	 Not for sale	Paint Black One Pack For Transmissions	1
39	1450/0001	Nipple Grease Straight 1/8" < Supersession TO REMAIN IN SITU ON	4