




389490

1	827/80139	Glass front screen,tinted with shade band Supersession > 332/H1528 found in supersession chain	1
1	827/80223	Glass front screen,tinted without shade band	1
2	827/80141	Glass left hand front quarter light Supersession >	1
3	827/80142	Glass right hand front quarter light Supersession >	1
4A	331/23360	Seal rear window lefthand flat glass 3563mm < Supersession	1
4	827/80248	Glass Left side window, flat <July 2003	1
4	827/80269	Glass Left side window flat >JULY 2003 2-holes 75mm higher-to suit rear window catch	1
5A	331/23362	Seal rear window right hand flat glass 3286mm	1
5	827/80249	Glass right side window flat	1
6A	331/23358	Seal door 4260mm long < Supersession	1
6	827/80143	Glass left hand door tinted Supersession >	1
7A	331/25558	Seal side window rh lower 2544mm long	1
7	827/80152	Glass lower side window right hand	1
8A	331/23363	Seal side window rh upper 3492mm long	1
8	827/80151	Glass upper side door right hand	1
9	⊘ Not for sale	NSP	1
10	813/10169	Gasket window stop 3cx cab	5
11	813/10167	Gasket window-hinge 3cx cab Flat glass	7
12	⊘ Not for sale	'See Remark' Not fitted use with curved glass only	0

