






550190

A	3	Link TBA	1
1	KRJ1600	Valve filter relief Supersession >	1
2	333/K8611	Element Return Filter, 10 Micron (1000 Hours) <i>From 15/11/2013</i> For Machine Without Plexus Filter	1
2	KRJ1599	Element filter return <i>To 14/11/2013</i> Supersession > For Machine With Plexus Filter 335/G2059 found in supersession chain	1
3	6059/0008R	Washer plain	8
5	1316/0405Z	Screw M10 X 20 < Supersession	4
6	⊘ Not for sale	Spring compression > No Longer Available	1
7	LBQ1353	O Ring < Supersession	1
8-4	C4E7901	Spanner	1
8	KNJ0610	Breather air	1
8-3	KNJ0611	Element filter Supersession >	1
8-1	KNJ0612	Strainer	1
8-2	LBQ0322	O Ring < Supersession	1
9	JNJ0055	Tank hydraulic fluid > No Longer Available	1
10	KRJ2645	Cover	1
11	⊘ Not for sale	Cover assembly Supersession > Used with breaker.	1
11	KNJ0962	Cover	1
12	LBQ1653	O Ring < Supersession	1

13	1316/0407Z	Bolt High Strength < Supersession	4
14	KNJ0589	Strainer suction	1
15	KHH0040	Plate Shim T=0.03"	0
16	KHH0137	Shim Plate	0
17	1316/0709Z	Screw < Supersession	4
18	JHP0043	Washer M16 < Supersession	4
19	1316/0505Z	Screw M12x20 < Supersession	1
20	KNJ0153	Adapter elbow	2
21	KNJ0154	Hose nylon	1
22	UBJ0399	Bush	1
23	KHJ0362	Tap drain	1
24	1420/0009Z	Washer (M12) < Supersession	1