




214 [T0] > B2-5-2 WINDOW, REAR TINTED GLASS



1	125/15900	Frame rear window Supersession >	1
1A	993/99591	Handle spring loaded Supersession >	2
2	827/30238	Glass rear window tinted <M405929 > No Longer Available	1
2	827/30287	Glass rear window tinted	1
3	926/12403	Glazing seal rear window < Supersession	1
4	916/04400	Bearing	2
5	123/02475	Carrier Bearing	2
6	1370/0303Z	Nut Lock M10 Supersession >	4
7	1420/0008Z	Washer Plain M10 Supersession >	8
8	123/02810	Link rear window left hand	1
9	123/02811	Link rear window right hand	1
10	1315/3716Z	Bolt M16 x 70mm	2
11	1370/0603Z	Nut Lock, M16 < Supersession	2
12	1420/0011Z	Washer (M16) < Supersession	6
14	122/06615	Cap < Supersession	4
15	123/02550	Strut gas Supersession > 331/20895 found in supersession chain	2
16	1420/0007Z	Washer (M8) Supersession >	8
17	913/01102	Clip Safety < Supersession	4
18	821/00318	Circlip	2

19	926/14900	Seal Rubber < Supersession	0
20	823/00223	Washer Rubber	2
21	1420/0009Z	Washer Plain M12 < Supersession	2
22	120/93201	Handle Righthand (M6) < Supersession	1
22	120/93202	Handle Lefthand < Supersession	1
23	2102/0407	Pin Tension	2
24	1370/0101Z	Nut (M6) Supersession >	2
25	835/00026	Plug	2
26	831/00099	Bearing Self Lubricating	4
27	913/00026	Clip retaining Supersession >	2
28	1420/0008Z	Washer Plain M10 Supersession >	2
29	120/83701	Stud Welded to cab frame.	2