


[https://servicepro.jcb.com/products/793991813529601602/parts?filters=%7B"activePage"%3A"51b093f9-cb73-4c8c-aa10-da508b622e1d"%2C"s...](https://servicepro.jcb.com/products/793991813529601602/parts?filters=%7B%22activePage%22%3A%2251b093f9-cb73-4c8c-aa10-da508b622e1d%22%2C%22...)

**231201**

1	⊘ Not for sale	Case timing Supersession >	1
2	02/200022	Gasket t/case to block Supersession > ALTERNATIVE 02/202326 found in supersession chain	1
2	⊘ Not for sale	Gasket t/case to block Supersession > 02/202326 found in supersession chain	1
3	02/190033	Gear idler assembly < Supersession	1
4	:02/192016	Bush < Supersession	1
5	02/100041	Hub < Supersession	1
6	02/291073	Screw	3
7	02/201288	Plate Supersession >	1
8	02/290014	Gear idler, oil pump	1
9	:02/290006	Bush < Supersession	1
10	02/290028	Shaft idler, oil pump Supersession >	1
10A	2102/0813	Pin tension < Supersession	1
11	02/100328	Circlip < Supersession	1
12	02/200104	Washer	1
13	826/00869	Screw Flange Head	8
14	02/291017	Screw	4

<https://servicepro.icb.com/products/793991813529601602/parts?filters=%7B%22activePage%3A%51b093f9-cb73-4c8c-aa10-da508b622e1d%22%2C%22...> 4/5

<https://servicepro.jcb.com/products/793991813529601602/parts?filters=%7B%22activePage%22%3A%2251b093f9-cb73-4c8c-aa10-da508b622e1d%22%2C%22...> 5/5