




|     |                |                                                                                                                 |    |
|-----|----------------|-----------------------------------------------------------------------------------------------------------------|----|
| A   | 128/13637      | Window assembly,rear as supplied<br><July 2003<br>Supersession >                                                | 1  |
| A   | ⊘ Not for sale | Window assembly,rear as supplied<br><M944200<br>Supersession ><br>Left lock bar 75mm higher-to match side glass | 1  |
| A   | 128/14092      | Window assembly, rear as supplied<br><M947217<br>Supersession >                                                 | 1  |
| A   | 128/14450      | Window assembly- rear as supplied<br>Supersession >                                                             | 1  |
| 1   | ⊘ Not for sale | None serviced part                                                                                              | 1  |
| 2   | ⊘ Not for sale | None serviced part                                                                                              | 1  |
| 3   | :335/03712     | Bar torsion                                                                                                     | 1  |
| 4   | :331/28221     | Seal rear window left hand end                                                                                  | 1  |
| 5   | :331/28222     | Seal rear window right hand end                                                                                 | 1  |
| 6   | :331/28223     | Roller Plastic                                                                                                  | 2  |
| 7   | :331/28224     | Block roller<br>Supersession >                                                                                  | 2  |
| 8   | :331/28226     | Bracket pivot<br>Supersession >                                                                                 | 2  |
| 9   | ⊘ Not for sale | Glass rear window<br><M944200<br>> No Longer Available                                                          | 1  |
| 9   | :827/80287     | Glass rear window<br><M947217<br>Supersession >                                                                 | 1  |
| 9   | :827/80310     | Glass rear window<br>< Supersession                                                                             | 1  |
| 10  | :331/28233     | Latch LH                                                                                                        | 1  |
| 10A | :331/43562     | Capscrew encapsulated<br>holds 7,8,10 & 11 to frame                                                             | 12 |
|     |                |                                                                                                                 |    |

|     |            |                                                             |   |
|-----|------------|-------------------------------------------------------------|---|
| 11  | :331/28235 | Latch RH                                                    | 1 |
| 12  | :331/28239 | Bar locking<br>Supersession >                               | 2 |
| 13  | :904/20260 | Seal rear window,bottom<br>< Supersession                   | 1 |
| 14  | :331/28215 | Strut gas 287 closed, 475 open                              | 2 |
| 15  | :904/20261 | Seal rear window,side<br><M944217<br>< Supersession         | 2 |
| 15  | :904/20302 | Seal window side seal<br>< Supersession                     | 2 |
| 16  | :904/20241 | Seal rear window top                                        | 1 |
| 17  | :331/33723 | Boot left hand,rubber<br>Supersession >                     | 1 |
| 18  | :331/33725 | Boot right hand,rubber<br>Supersession >                    | 1 |
| 20  | 826/10875  | Capscrew M8 x 12<br>< Supersession                          | 2 |
| 20A | 1370/0203D | Nut Lock M8<br>< Supersession<br>fit to item 20 if required | 2 |
| 21  | 826/10878  | Screw Button Head                                           | 3 |
| 22  | 823/10409  | Washer Black                                                | 3 |
| 23  | 823/00529  | Washer M8                                                   | 4 |
| 23  | 1420/0007D | Washer M8<br>< Supersession                                 | 2 |
| 24  | 826/10948  | Capscrew                                                    | 4 |
| 25  | 813/10216  | Gasket foam, left hand C-post                               | 1 |
| 26  | 813/10201  | Gasket Foam, right hand C-Post                              | 1 |
| 27  | 926/46400  | Strip cab sealing 8 x 3 thk x 100 long<br>< Supersession    | 2 |
| 28  | 4103/3201  | Adhesive Sika 552, 310ml Black<br>> No Longer Available     | 0 |
| 29  | 4104/1203  | Cleaner primer SIKA 205 250ml<br>Supersession >             | 0 |

