




|    |                |                                                                                          |   |
|----|----------------|------------------------------------------------------------------------------------------|---|
| A  | 25/220589      | Valve joystick control Transmission Rexroth                                              | 1 |
| 1  | 25/220681      | Handle type ST                                                                           | 1 |
| 2  | 25/220682      | Kit push button covers<br>Supersession ><br><b>25/207011</b> found in supersession chain | 1 |
| 3  | 25/220684      | Kit lever                                                                                | 1 |
| 4  | 25/220683      | Boot rubber                                                                              | 1 |
| 6  | 25/220685      | Kit cardan<br>< Supersession                                                             | 1 |
| 7  | 25/220686      | Plate retaining                                                                          | 1 |
| 10 | 25/220687      | Kit plunger with NBR seals<br>< Supersession<br>kit is 2 plunger sets                    | 2 |
| 12 | ⊘ Not for sale | None serviced part<br>< Supersession                                                     | 1 |
| 13 | ⊘ Not for sale | None serviced part<br>< Supersession                                                     | 1 |
| 18 | 25/220691      | Body upper                                                                               | 1 |
| 19 | 25/220690      | Kit seal                                                                                 | 1 |
| 20 | 25/220692      | Kit flange<br>Supersession >                                                             | 1 |
| 21 | 25/220693      | Kit flange seals<br>< Supersession                                                       | 1 |
| 40 | ⊘ Not for sale | None serviced part<br>< Supersession                                                     | 1 |
| 41 | ⊘ Not for sale | None serviced part<br>< Supersession                                                     | 1 |