


2026/1/20 10:34:08



1400 > B2-9-1 WINDOW, REAR METAL FRAME



073660

1	121/07000	Frame rear window	1
2	121/06900	Handle > No Longer Available	1
3	121/07501	Link > No Longer Available	1
4	913/01100	Pin clevis < Supersession	1
5	:913/01102	Clip Safety < Supersession	3
6	1420/0007Z	Washer (M8) Supersession >	2
7	121/07502	Shaft	2
8	814/00197	Spring	1
9	2103/0709	Pin split 1/8 x 1	2
10	916/04000	Bearing < Supersession	2
11	916/04000	Bearing < Supersession	2
12	121/36900	Bar pivot left hand	1
13	121/36800	Bar pivot right hand	1
14	657/00018	Tube	1
15	2102/0613	Pin tension	1
16	2102/0609	Pin tension	1
17	926/06701	Seal < Supersession	0
18	827/20080	Glass rear clear	1
18	827/30120	Glass rear tinted > No Longer Available	1

19	926/06001	Glazing seal rear window < Supersession	0
20	120/93201	Handle Righthand (M6) Supersession >	1
20	120/93202	Handle Lefthand < Supersession	1
21	1420/0009Z	Washer (M12) < Supersession	2
22	2102/0407	Pin Tension	2
23	826/00694	Nut > No Longer Available	2